



1. PA UNIT



2. DRIVER UNIT



Required tool: Soldering iron, Screw drivers
Estimated work-time : 0.5 ~ 1 hour

Parts:

UNIT	REF No.	Old part No.	Old part name		New part No.	New part name
DRIVER	MP38	8930065910	2427 EARTH SPRING	=>	8930065911	2427 EARTH SPRING-1
DRIVER	MP41	8930065910	2427 EARTH SPRING	=>	8930065911	2427 EARTH SPRING-1
PA	MP251	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING
PA	MP305	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING
PA	MP402	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING
PA	MP403	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING
PA	MP404	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING
PA	MP421	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING
PA	MP503	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING
PA	MP871	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING
PA	MP901	8930014140	GROUNDING SPRING(D)	=>	8930071160	2427 F-EARTH SPRING